

NART

KREENHOLM SAFETY INSTRUCTIONS

Following these guidelines will help you minimize risks and stay safe during your visit to the Kreenholm textile manufactory. Your safety is ultimately your responsibility.

Preparation and navigation

- Access to the Kreenholm site requires a special permit from the property owner. Request this permit in advance via NART staff and ensure all visitor names are included.
- Since the site lacks lighting, bring a flashlight and wear reflective clothing to enhance visibility.
- Carry valid identification at all times and familiarize yourself with the terrain before moving around.
- Stay alert and avoid areas with visible hazards such as pits, open manholes, or obstacles. Use your flashlight to illuminate your path.

Safety inside buildings

- Enter buildings cautiously and light your path with a flashlight.
- Avoid damaged floors, open pits, unsafe staircases, and use handrails where available.
- Be aware of structural hazards such as loose bricks, window frames, or glass that could fall. Roofing materials may be unstable, especially in windy conditions.

Restricted and dangerous areas

- Do not enter zones marked as restricted or dangerous.
- Report any unsafe conditions or hazards to the appropriate personnel immediately.
- Do not use exterior metal ladders as they are unsafe and may collapse.

Emergency situations

- If someone is injured, provide first aid if possible and report the incident without delay.
- Keep emergency contact numbers, including 112, readily accessible.
- Familiarize yourself with evacuation routes before entering the premises and evacuate quickly and safely in case of danger.

Items and alterations

- Removing objects or items from the Kreenholm area is strictly prohibited.
- Do not alter the space in any way, including moving items, opening windows, or adjusting doors.